



change the auto re-register from 3600 seconds down to 900 seconds

Also must load patch

Attached is the MX-Patch from Zultys for firmware 8.0.3 that fixes the problem of auto-reboots when calls are set to auto forward via AA.